

SOUTH COAST AIR QUALITY MANAGEMENT DISTRICT
21865 Copley Dr., Diamond Bar, CA 91765-4182

MONITORING & ANALYSIS
REPORT OF LABORATORY ANALYSIS

Page 1 of 2

TO Cher Snyder
ADEO, Engineering & Compliance

LABORATORY NO. 1602725-01

FACILITY ID NA

SAMPLE(S) DESCRIBED AS
Triggered Sample
Tedlar Bag: 001

DATE RECEIVED 1/27/16

PROJECT/ ST NO/ RULE 402

SAMPLING LOCATION
Highlands Community
Pool Parking Lot

REQUESTED BY Sumner Wilson

DATE ANALYZED 1/27/16

ANALYTICAL WORK PERFORMED, METHOD OF ANALYSIS AND RESULTS
Total Reduced Sulfur (TRS) by SCAQMD Method 307-91

	Result*
t-butyl mercaptan	< 1 ppb
tetrahydrothiophene (THT)	< 1 ppb
carbonyl sulfide	< 1 ppb
Total Reduced Sulfur	< 1 ppb

*Calibrated using methyl mercaptan

Date Approved: 2/2/16

Approved By: Rudy Eden

Rudy Eden, Senior Manager
Laboratory Services
(909) 396-2391

10-10

SOUTH COAST AIR QUALITY MANAGEMENT DISTRICT
21865 Copley Dr., Diamond Bar, CA 91765-4182

MONITORING & ANALYSIS
REPORT OF LABORATORY ANALYSIS

Page 2 of 2

SAMPLE(S) DESCRIBED AS

Triggered Sample
 Tedlar Bag: 001

LABORATORY NO. 1602725-01

REQUESTED BY Sumner Wilson

Total Reduced Sulfur (TRS) by SCAQMD Method 307-91
Quality Control Tests and Results Matrix

	Control (ppb)				Pre-Blank (ppb)
	Prepared	Measured	% Recovery		Measured
Methyl Mercaptan	1.01	0.90	89.6	Methyl Mercaptan	< 1 ppb
Ethyl Mercaptan	1.04	0.99	95.2	Ethyl Mercaptan	< 1 ppb
Isopropyl Mercaptan	1.04	1.07	103.4	Isopropyl Mercaptan	< 1 ppb
1-Propanethiol	1.03	1.04	101.0	1-Propanethiol	< 1 ppb
				Unknown	1.4*

Calibration Drift (ppb)

	Prepared	Measured	% Recovery
Methyl Mercaptan	30.15	28.42	94.3
Ethyl Mercaptan	31.20	29.49	94.5
Isopropyl Mercaptan	31.05	30.20	97.3
1-Propanethiol	30.90	29.62	95.9

*Calibrated using Methyl Mercaptan

**SOUTH COAST AIR QUALITY MANAGEMENT DISTRICT
SAMPLE ANALYSIS REQUEST**

DISTRICT INF
 INVOICE SOU
 LAP AUDIT
LABORATORY

1602725



TO: SCAQMD LAB: OTHER: _____
 SOURCE NAME: _____ Southern California Gas Co. _____ I.D. No. _____
 Source Address: _____ 12801 Tampa Ave _____ City: _____ Porter Ranch _____
 Mailing Address: _____ City: _____ Zip: _____ 91326 _____
 Contact Person: _____ Title: _____ Tel: _____

Analysis Requested by: _____ Sumner Wilson _____ Date: _____ 1/27/16 _____
 Approved by: _____ Jason Low _____ Office: _____ Budget #: _____ 44716 _____
 REASON REQUESTED: Court/Hearing Board Permit Pending Hazardous/Toxic Spill
 Suspected Violation Rule(s) 402 Other _____

Sample Collected by: _____ Mike Koch _____ Date: _____ 1/27/16 _____ Time: _____ 15:00 _____

REQUESTED ANALYSIS:

City/Location	Can#	Start day / time/ duration	Start vac	End vac
Highlands Community	<i>Accordion</i> Tedlar Bag 001	1-27-16 / 14:50/ 3min	NA	NA

Relinquished by	Received by	Firm/Agency	Date	Time
M. Koch	<i>[Signature]</i>	SCAQMD Lab	01/27/16	4:35 pm

Remarks: Grab Sample

Highlands community pool parking lot. Address: 12378 High Glen Way, Northridge CA 91326 (across from 12377)