

Exhibit 2 - Engine Summary

Amazon.com Services LLC (Facility ID 203446) ICE Equipment Description						
Permit to Operate	Unit No.	Make	Model	Rating (hp)	Meter Reading (hrs)	Total Usage (hrs) (5/18/2025 - 5/5/2026)
G80184	2813	Caterpillar	C18 ACERT	778	7842	2231
G80185	2976	Caterpillar	C18 ACERT	778	8136.2	4202.2
G80186	3195/3196 ^a	Caterpillar	C18 ACERT	778	7111.5/5941.7	3837.5
G80187	3030 ^b	Caterpillar	C18 ACERT	778	7414.7	6705.7

^a Engine 3195 was swapped with engine 3196 in March 27, 2026. An intermittent defect was identified with the main circuit breaker. Due to the presence of a live bus, it was unsafe to perform repairs in place. As a result, the breaker was removed from the unit and sent out for professional refurbishment. These engines are identical make/model and manufacturer year.

^b Engine 3030 has been turned off and locked out due to total hours approaching maximum permitted hours