

**Built Environment Testing** 

Report for:

Cynthia Berg South Coast Air Quality Management District 21865 Copley Drive Diamond Bar, CA 91765

Regarding: Eurofins Built Environment Testing West, LLC Project: 2025 LA Wildfires - Eaton Shepherd Church EML ID: 4042823

Approved by:

Ather Venegar Bucio

Approved Signatory Arthur Bucio

Dates of Analysis: Asbestos TEM - AHERA (40CFR Part 763, Subpart E, Appendix A): 04-24-2025

Service SOPs: Asbestos TEM - AHERA (40CFR Part 763, Subpart E, Appendix A) (EM-AS-S-8578) NVLAP Lab Code 200757-0

All samples were received in acceptable condition unless noted in the Report Comments portion in the body of the report. Due to the nature of the analyses performed, field blank correction of results is not applied. The results relate only to the samples as received and tested.

Eurofins Built Environment Testing West, LLC ("the Company"), a member of the Eurofins Built Environment Testing group of companies, shall have no liability to the client or the client's customer with respect to decisions or recommendations made, actions taken or courses of conduct implemented by either the client or the client's customer as a result of or based upon the Test Results. In no event shall the Company be liable to the client with respect to the Test Results except for the Company's own willful misconduct or gross negligence nor shall the Company be liable for incidental or consequential damages or lost profits or revenues to the fullest extent such liability may be disclaimed by law, even if the Company has been advised of the possibility of such damages, lost profits or lost revenues. In no event shall the Company's liability with respect to the Test Results exceed the amount paid to the Company by the client therefor.

# **Eurofins Built Environment Testing West, LLC**

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (833) 465-5857 www.eurofinsus.com/Built

Client: South Coast Air Quality Management DistrictDate of Sampling: 04-22-2025C/O: Cynthia BergDate of Receipt: 04-23-2025Re: 2025 LA Wildfires - Eaton Shepherd ChurchDate of Report: 04-24-2025

# ASBESTOS TEM AHERA REPORT

20139534-1       7200       0.04       4       0.001       0       No Structures Detected       0       0       <24.752       <0.001         DL942182 Asbestos       Sample       0       0       0       0       <24.752       <0.001         04/24/2025       0       0       0       0       0       0       <24.752       <0.001	Lab ID-Version‡ Location Analysis Date	Volume (liters)	Area Analyzed (mm2)	Grid Openings Examined	Analytical Sensitivity (S/cm3)		Asbestos Types		Structures S) >=0.5-<5µm		estos ntration S/cm3
	DL942182 Asbestos Sample	7200	0.04	4	0.001	0	No Structures Detected	0	0	<24.752	<0.001

§ Asbestos Concentration has been rounded to three significant figures to reflect analytical precision.

The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government.

Digital images of diffraction patterns and copies of analytical bench sheets pertaining to this project are available upon request. The estimated measurement of uncertainty and 95% confidence interval for the test results are also available upon request.

The laboratory is not responsible for data collected by personnel who are not part of the laboratory. Results reported in both structures/cm3 and structures/mm2 are dependent on the volume of air sampled and measured by non-laboratory personnel.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

### **Eurofins Built Environment Testing West, LLC**

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (833) 465-5857 www.eurofinsus.com/Built

Client: South Coast Air Quality Management District Date of Sampling: 04-22-2025 C/O: Cynthia Berg Re: 2025 LA Wildfires - Eaton Shepherd Church

Date of Receipt: 04-23-2025 Date of Report: 04-24-2025

# **ASBESTOS TEM AHERA REPORT**

#### PROJECT ANALYST AND SIGNATORY REPORT

**Project Analyst** 

Mar Jengan Bucio

Analyst: Arthur Bucio

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins Built Environment Testing West, LLC



CHAIN OF CUSTODY 🎲 eurofins						WEATHER Fog Rai				Rain Snow Wind Clear															
www.eurofinsus.com/Built Built Environm				2 Light Moderate Heavy										REQUESTED SERVICE									-		
Marlton, NJ: 3000 Lincoln Dr E, Ste. A, Marlton, NJ 08053 * (866) 871-1984 Phoenix, AZ: 1501 West Knudsen Drive, Phoenix, AZ 85027 * (800) 651-480; Burlingame, CA: 111 Anza Blvd, Suite 122, Burlingame, CA 94010 * (866) 88										Spore Trap	Ţ	Tape wab, E	. 8		Culturable oCassette <sup>®</sup> Andersen, SA wab, Water, Bulk, Dust, So , Contact Plate										
CONTACT INFORMA					TION																				
Company:	South Coast	Air Quality Manageme	nt District (42519)	21865 C ddress:	Copley Driv	ve Diamond Bar, CA	A 91	1765								(eµa)									
Contact:	Cynthia Berg	g					_							( uus	1	Bacter				17400)					
Phone:	909-396-218	1	SI	pecial Instru	ictions:				<i>c</i>		t				di di	and Surface	(BDUB)		-	Count (NIOSH					
	PI	ROJECT INFORMATI	ON			TURN AROUND TIME			E CODES - (TAT)			Evem (Outelitetive)	direct exam	<u>c</u>	+ A8	r and S	e/Abs			Count					
Project ID:	2025 LA	Wildfires			STD - St	STD - Standard (Default)			Rushes received after 2pm			(Bill)	direct	anina	OI SU	sble Air	Seno	e	est)	Fiber			(test)		
Project Description:	Eaton S	hepherd Church	A . 27.		ND - Nex	t Business Day	or on weekends, will be considered received the				oic Exam	count o	0,00	(Gen	Cultur	V (Pre	Scre	acify t	rborne	_ 4	(test)	ecify			
Project Zip Code:	91001	Sampling Date/Time	P 4/28/	28 000	SD - Same Business Day			next business day. Please				poic H	spore of	rizatio	Fungi	ounts	E col	wage	se spe	CM N	- PLA	pecify	ds es		
PO Number:	2025000028 Sampled				WH - Weekend/Holiday/ASAP			<ul> <li>alert us in advance of weekend analysis needs.</li> </ul>			ap Analysis logical part	CLOSE	ive sp	Surfa	e Air	o pue	iform,	ay-Se	(plea	Air - F	A Bulk	888 8	(plea		
SAMPLE ID DESCRIPTION Sample (Below)			TAT (Above)	Total Volume/Area (as applicable)	Π	NOTES Time of day, Temp, RH, etc.)			Spore Trap Analysis Other biological part	Diract Mi	Quantitative	Dust Characterization 1-Media Surface Fund (Genus ID + Acn	Culturable Air Fungi (Genus ID + Asp.	Grem Stain and Counts (Culturatie Air	Legionella culture Total Coliform, E.coli (Presence/Absence)	QuantiTray-Sewage Screen	OTHER: (please specify test)	Asbestos in Air - PCM Airborne Fiber	Asbestos Bulk - PLM Lead (Ph) - Flame AA	PCR (please specify		EM-			
DL942	182 50	Asharta etime offisi	5 50mb 15 005-51			9.20 m <sup>3</sup>		f and	- 5	:02 (pm.															
	1	SAMPLE TYPE COL	ES			RELINQUISH	EDI	BY	DAT	E & TIME	-	-	F	ECE	IVED	BY			-	DA	TE 8	L TIM	E	i	
BC - BioCassette <sup>™</sup> CP - Contact Plate         T - Tape         O - Other:           A1S - Andersen         ST - Spore Trap         SW - Swab           SAS - Surface Air Sampler         B - Bulk         SO - Soil			JEBerveri		04		13/25	Brenda F.						$\sim$		11:05 91									
NP - Non-potable Water		P - Potable Water	D - Dust						10	131															

By submitting this Chain of Custody, you agree to be bound by the terms and conditions set forth at https://www.eurofinsus.com/environment-testing/built-environment/resources/sampling-guides-and-forms/ Copyright © 2022 Eurofins EPK Built Environment Testing, LLC