

**Built Environment Testing** 

Report for:

Cynthia Berg South Coast Air Quality Management District 21865 Copley Drive Diamond Bar, CA 91765

	Eurofins Built Environment Testing West, LLC
Regarding:	Project: 2025 LA Wildfires - Eaton Fire Station 11; Eaton Fire Station 11
	EMĹ ID: 4061415

Approved by:

enthor Venegar Bucio

Approved Signatory Arthur Bucio

Dates of Analysis: Asbestos TEM - AHERA (40CFR Part 763, Subpart E, Appendix A): 05-07-2025

Service SOPs: Asbestos TEM - AHERA (40CFR Part 763, Subpart E, Appendix A) (EM-AS-S-8578) NVLAP Lab Code 200757-0

All samples were received in acceptable condition unless noted in the Report Comments portion in the body of the report. Due to the nature of the analyses performed, field blank correction of results is not applied. The results relate only to the samples as received and tested.

Eurofins Built Environment Testing West, LLC ("the Company"), a member of the Eurofins Built Environment Testing group of companies, shall have no liability to the client or the client's customer with respect to decisions or recommendations made, actions taken or courses of conduct implemented by either the client or the client's customer as a result of or based upon the Test Results. In no event shall the Company be liable to the client with respect to the Test Results except for the Company's own willful misconduct or gross negligence nor shall the Company be liable for incidental or consequential damages or lost profits or revenues to the fullest extent such liability may be disclaimed by law, even if the Company has been advised of the possibility of such damages, lost profits or lost revenues. In no event shall the Company's liability with respect to the Test Results exceed the amount paid to the Company by the client therefor.

Client: South Coast Air Quality Management District C/O: Cynthia Berg Re: 2025 LA Wildfires - Eaton Fire Station 11; Eaton Fire Station 11

## ASBESTOS TEM AHERA REPORT

## **Eurofins Built Environment Testing West, LLC**

2841 Dow Avenue, Suite 300, Tustin, CA 92780 (833) 465-5857 www.eurofinsus.com/Built

Date of Sampling: 05-04-2025 Date of Receipt: 05-06-2025 Date of Report: 05-07-2025

Lab ID-Version‡ Location Analysis Date	Volume (liters)	Area Analyzed (mm2)	Grid Openings Examined			Asbestos Types		Structures S) >=0.5-<5µm	Concer	estos ntration S/cm3		
20242313-1 DL942181 Asbestos Sampling 05/07/2025	2860	0.04	4	0.003	0	No Structures Detected	0	0	<24.752	<0.003		
Comments:												

§ Asbestos Concentration has been rounded to three significant figures to reflect analytical precision.

The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government.

Digital images of diffraction patterns and copies of analytical bench sheets pertaining to this project are available upon request. The estimated measurement of uncertainty and 95% confidence interval for the test results are also available upon request.

The laboratory is not responsible for data collected by personnel who are not part of the laboratory. Results reported in both structures/cm3 and structures/mm2 are dependent on the volume of air sampled and measured by non-laboratory personnel.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Client: South Coast Air Quality Management District C/O: Cynthia Berg Re: 2025 LA Wildfires - Eaton Fire Station 11; Eaton Fire Station 11

## ASBESTOS TEM AHERA REPORT

## PROJECT ANALYST AND SIGNATORY REPORT

**Project Analyst** 

Mar Jungar Bucio

Analyst: Arthur Bucio

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

<sup>‡</sup> A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Eurofins Built Environment Testing West, LLC

Eurofins Built Environment Testing West, LLC 2841 Dow Avenue, Suite 300, Tustin, CA 92780

(833) 465-5857 www.eurofinsus.com/Built

Date of Sampling: 05-04-2025 Date of Receipt: 05-06-2025 Date of Report: 05-07-2025



CHAIN OF CUS		fins			WEA		Fog Ra	ain Snow	Wind Clear				1	REOL	JEST	ED S	SERVI	CES		1			
www.eurofinsus.com/Built Built Environment Testing					Non	Non-Culturable Culturable																	
Marlton, NJ: 3000 Lincoln Dr E, Ste. A. Marlton, NJ 08053 * (866) 871-1984 Phoenix, AZ: 1501 West Knudsen Drive, Phoenix, AZ 85027 * (800) 651-480 Burlingame, CA: 111 Anza Blvd, Suite 122, Burlingame, CA 94010 * (866) 88						derate				Spore Trap		Tape, ab, Bu	Bio	vab, W	Cassette <sup>™</sup> Andersen, S ab, Water, Bulk, Dust, Contact Plate				Oth	er Re	eque		
		CONTA		TION		- Y																	
Company:	ast Air Quality Managemen	nt District (4251)	9) 21865 ( Address:	Copley Driv	e Diamond Ba	r, CA 9	)1765							) Destantal	acteria)				7400)				
Contact:	special Instructions:										o. spp.	1.2											
Phone: 909-396-	2181									ent l	ê	ε	+ Asp	sp. s	Suma	senc			Count (NIOSH				
	PROJECT INFORMATI	ON		TURN AROUND TIME CODES - (TAT)					plen	littati	t exa	ė	+	ur and	ce/AB			Cour					
	A Wildfires			STD - Standard (Default) Rushes received after 2p						dins -	0 0	direc	(Genus ID + Asp.	us IC	appe	esend	reen / test)		Fiber		( toel)		
Project Eator	Fire Station 11			ND - Next	Business Da	y.			ds, will be beived the	icles	xam	onut	lla.	(Gen	Congra	ď,	Scre		rbome	<	rtest		
the second se	91001 Sampling Date/Time: 05/04/15 0223			SD - Sam	e Business D	ay	next bi	usiness d	lay. Please	alysis I part	pic E	ore c	e Fungi	ißun	and an	Ecol	e spe		CM AI	MeA	ise specify test)	000	
PO Number: 20250	Compled	Sampled (17)			WH - Weekend/Holiday/ASAP weekend analysis need					ap An	croscc	ive sp	Surfac	e Air F	and Co	iform,	ay-Ser (pleas		Air - P	) - Fla	ase s	pand) a	
SAMPLE ID	Sample			TAT (Above)	Total Volume/Ar (as applicab		NOTES (Time of day, Temp, RH, etc.)			Spore Trap Analysis Other biological particles - supplement	Direct M	Quantitative spore count direct exam	1-Media Surface	Culturable Air Fungi (Genus ID + Asp.	Gram stain and countils (culturable Air and Surtace Legitornella culturre	Total Coliform, E.coli (Presence/Absence)	QuantiTray-Sewage Screen OTHER: (please specify test)		Asbestos in Air - PCM Airbo Asbestos Bulk - PLM	Lead (Pb) - Flame AA	PCR (please specify test) Alternens (please specify		M- HERA
02942181	aslacstes some	is-P		ND	2.86 m	3 .	fas =	5.00	1 pm													Х	
5	aslarstes some	4/25 09	32			·P	over.	Fil =	short min thons		-												
	1					r	un e	. 970	min						_								
						- 1	any	Ond	tions		+			++						+			1.1
							· · · ·				+			+-+		++		$\left  \right $		+		+	
											+-		+	++		$\left  \right $				+		-	
											+			++	+					++		+	
						1					1			$^{++}$		$\uparrow \uparrow$				17			
	1	-									t												
															_							_	
· *											-							1		$\square$			
						_					+			+		$\left  \right $		-		+			
		)EC			RELINQU		BV	DAT	TE & TIME	╠╧		PI	CEI	VED	BV			⊢	DAT	E 8	TIME		1
SAMPLE TYPE CODES   BC - BioCassette <sup>™</sup> CP - Contact Plate T - Tape O - Other:								_					,		,	7			140	1	05	-	
BC - BioCassette <sup>™</sup> A1S - Andersen	ST - Spore Trap	SW - Swab	o - oner.		-Esen	ver	-	5/	4125 352pat	# C	a.~	~0(	C	rl	L/	Ų	-	19	5/6	50	5		
SAS - Surface Air Samp		SO - Soil			00011	-			2-pat				1		V				-	And the second second	-		
NP - Non-potable Water		D - Dust			+	1																	

.

By submitting this Chain of Custody, you agree to be bound by the terms and conditions set forth at https://www.eurofinsus.com/environment-testing/built-environment/resources/sampling-guides-and-forms/ Copyright © 2022 Eurofins EPK Built Environment Testing, LLC