RULE 1173 DELAY OF REPAIR REPORT

YEAR: 2027 **QUARTER:** 1 (JAN-MAR)

Please submit all Rule 1173 reports electronically to: Rule1173Reports@aqmd.gov

Facility Name: Example Facility
Facility ID#: 123456
Report Date: April 15, 2026
Fac. Address: 21865 Copley Dr
City/Zip: Diamond Bar, CA 91765
Contact Name: John Doe, Environmental Specialist
Phone: (800) 555-1212
Email: jdoe@examplefacility.com

Component Data				Initial Inspection				Re-Inspection (if applicable)				Most Recent Inspection			
ID	Type	Svc	Location	Date/Time	ppm	Visible Leak?	Visible Vapor?	Date/Time	ppm	Visible Leak?	Visible Vapor?	Date/Time	ppm	Visible Leak?	Visible Vapor?
Example 1: Essential Component Valve found above leak standard															
12345.01	Valve	G/V	1.5" upstream Unit 200	7/15/26 9:30	250	N/A	N/A	N/A				1/15/2027 10:15	251	N/A	N/A
Example 2: Essential Component Flange found above violation, partially repaired															
8675309.01	Fitting (Flange)	LL	Unit 300	7/15/26 10:30	25000	N/A	N/A	7/16/2026 14:55	350	N/A	N/A	1/15/2027 13:30	349	N/A	N/A
Example 3: Essential Component Connector found above leak standard. Also inaccessible component															
E3490.00	Fitting (Connector)	G/V	NSD E-105A (Inacc)	9/15/26 15:15	150	N/A	N/A	N/A				9/15/26 15:15	150	N/A	N/A
Example 4: Essential Component Pump (light liquid) found with visible leak via AVO inspection															
P345.00	Pump (Light Liquid	LL	OH F-224	2/15/26 11:15	N/A	Yes	N/A	2/16/2026 8:45	450	No	N/A	1/15/2027 9:45	455	N/A	N/A
Example 5: Essential Component Compressor found with visible vapor via OGI inspection															
C0021.00	Compressor	G/V	Unit 2	10/1/26 7:15	N/A	N/A	Yes	10/1/2026 15:50	425	N/A	N/A	1/15/2027 11:15	430	N/A	N/A
Example 6: Fin fan plug found above leak standard															
FF012.117	Fin Fan	LL	FF #12, Plug #117	4/7/26 8:50	1000	N/A	N/A	N/A				4/7/2026 8:50	1000	N/A	N/A
Example 7: Fin fan plug found above violation standard															
FF109.041	Fin Fan	LL	FF #109, Plug #41	1/13/26 14:30	25000	N/A	N/A	1/20/2026 7:45	750	N/A	N/A	1/18/2027 12:45	755	N/A	N/A
Example 8: Fin fan plug found with visible leak via AVO inspection															
FF079.202	Fin Fan	LL	FF #79, Plug #202	8/26/26 6:04	N/A	Yes	N/A	9/8/2026 16:10	1500	No	N/A	9/8/2026 16:10	1500	N/A	N/A
Example 9: Fin fan plug found with visible vapors via OGI															
FF144.179	Fin Fan	LL	FF #144, Plug #179	12/7/26 13:13	N/A	N/A	Yes	12/17/2026 10:55	910	N/A	No	1/15/2027 7:55	915	N/A	N/A